

2837

HARVARD II

(WRITE-OFF)

1941

S.E. TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
11.5.41	1 "C3"	Camp Borden	0930	15FTS, sC85	11/5	LAC W. G. Sharpe			
28.9	2 "C1/2"	Camp Borden Bld	0230	15FTS, sC154	29/9	Lt. J. D. Lester	Solo		
22.10.	3 "A"	3/4 m. N.C. Borden A.	2245	4/2 below	19.1.42	Lt. A. M. Howe	Solo		
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re acc. 3 has been slightly injured - apparently suffered at time from a spell similar to that prominent in his childhood days. Recommended not to fly again as a crew.

The above information taken from Precis written by
 Lt. Col. E. C. Rappell on file 1100-28-37 dated 19.1.42

