

2839

HARVARD 11

(WRITE-OFF)

1941

S.E. TRAINER

REGISTRATION NO.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS NO.

## OVERHAUL DATA

| DATE | REASON | DONE BY | REQ'N No. | COST | HOURS SINCE NEW | DATE COMPLETED | ALLOTMENT |
|------|--------|---------|-----------|------|-----------------|----------------|-----------|
| 1    |        |         |           |      |                 |                |           |
| 2    |        |         |           |      |                 |                |           |
| 3    |        |         |           |      |                 |                |           |
| 4    |        |         |           |      |                 |                |           |
| 5    |        |         |           |      |                 |                |           |
| 6    |        |         |           |      |                 |                |           |
| 7    |        |         |           |      |                 |                |           |
| 8    |        |         |           |      |                 |                |           |
| 9    |        |         |           |      |                 |                |           |
| 10   |        |         |           |      |                 |                |           |
| 11   |        |         |           |      |                 |                |           |
| 12   |        |         |           |      |                 |                |           |

## ACCIDENT RECORD

| DATE    | CATEGORY | PLACE            | TIME | REPORT REFERENCE | DATE | RANK & NAME OF PILOT | No. IN CREW | DISPOSAL  | DATE SERV. |
|---------|----------|------------------|------|------------------|------|----------------------|-------------|-----------|------------|
| 18.6.41 | B        | Dumfries         | 1000 | #6 SFTS. 8 A339  | 18/6 | LAC R J Calder       |             |           |            |
| 17.4.42 | "A"      | Im W Fisherville | 1400 | 6 SFTS. 8 A644   | 17/4 | Lac A L Rankin       | 1           | WRITE-OFF |            |
| 3       |          |                  |      |                  |      |                      |             |           |            |
| 4       |          |                  |      |                  |      |                      |             |           |            |
| 5       |          |                  |      |                  |      |                      |             |           |            |
| 6       |          |                  |      |                  |      |                      |             |           |            |
| 7       |          |                  |      |                  |      |                      |             |           |            |
| 8       |          |                  |      |                  |      |                      |             |           |            |

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Re Acc. 1. - Harvard 2839 overshot runway and collided with 2752.  
 Re acc. 2. - Eng. installed 9643/4773. Ac crashed and burned.  
 Pilot and occupant killed.

