

2852

HARVARD III

(WRITE-OFF)

1941

S. E. TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
20/9/41	A	Summerside	1420	#9SFTS, A 523	21/7	Lt. J. O'Donnell		Spares & produce	
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. acc. "1"

Cause of accident obscure, presumably air collision with Harvard 2693

20/7/41 - Inspection report from #9SFTS recommends this to be written off

Total Flying Time: - 332³⁵ hrs (auth Log Book)

