

2855

HARVARD II

1941

S.E. TRAINER

REGISTRATION NO.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURER'S NO.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
24-9-43		W. R. D. (W. Res)				24-3-44	# I.T.C.
6-5-44	rec'd & moved					1-7-44	# I.T.C. DR
2-9-50	open R.M. 6	Weston A.C. CDW	501660			23-10-51	PC
4 Apr 55	major inspection	W. R. D. (W. Res)					
	outstanding work						
	special inspection						
	necessary repairs						

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
2/12/41	"C2"	Summerside	1550	#9 SFTS, A168	2/13	AC M. W. J. J. J.			
3-7-41	"C1"	Summerside PEG	0930	#9 SFTS, S A 486	3/7	Sgt. M. W. J. J.	1		
5-11	"C2"	Summerside A.C.	1700	#9 SFTS, S A 738	5/11	Sgt. M. W. J. J.			
9-1-42	"C1"	Summerside A.C.	1415	#9 SFTS, S A 9	9/1	Sgt. M. W. J. J.	1		

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Re Acc 1. Pupel started to taxi into Harvard 2515. Instructor applied brakes to avoid collision and aircraft went up on nose. Re acc 4. Instructor while taxiing from front cockpit failed to notice that preceding aircraft had stopped. Applied brakes but owing to icy conditions, taxied into other aircraft. Engine installed - Napco S3H-1 no. 8513/4372.

28-8-42 - intercommunication installation complete. 6 R.R. no. 24-6-7189 on 500-1-3.

6 Jan 48 - Refug. 5.77. 2883.45. 7.50. 382.20. Condition. Prod. Return. Sent a/c allotted 6/14 for mod ED 05-55A-6B/14 and 6B/15 (tail wheel declutching and electrical junction box) auth. 206 314 d 21 Dec 55. Refug 17 Nov 56.

## REMARKS

## RECORD OF WRITE-OFF

APPLICATION REC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

## DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

## AIRCRAFT RECORD CARD

FIRST ENTRY AT		DATE	TRANSFER ORDER No.		
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
9.6.42	Stored Reserve #1 J.C.	T.O. 1216	17 Nov 54	SR Lincoln Park	To-707
18.6.	#1 J.C. #65735	T.O. 1426	4 Apr 55	WR Lincoln Park	To-407
24.9.43	Northrup Ad	To C. 1636	16 May 55	TC (Lincoln Park)	To 505
24.3.44	#1 J.C.	T.O. 19364	31 Aug 56	SR Lincoln Park	To 873
6.5.44	#6 R.D. (W. Res)	T.O. C. 243			
1.7.44	Stored Reserve #1 T.C.	T.O. 14464			
7.9.44	#1 T.C.	T.O. 15939			
15.1.45	No. 1 A.C.	T.O. 17863 (C3)			
24.4.45	STORED RESERVE No. 1 A.C.	T.O. 12306			
27.11.45	S.R.M.C. (REMS Denmark)	To-MC15887			
22 Dec 50	NOIATSU (Winton a/c)	To 1256			
23 Oct 51	AC (Winton) 16095 2470	To-1457			

REMARKS 7/7/45:- STORED RESERVE - FROZEN SERIES.

Ref No 38190

U.K. Contribution

2/1/41 Recd from North American Aviation

9277/466T

100336

ENGINE TYPE	WASP S3H-1	UNITS	1	AIRSCREW TYPE (CODE)		REF. No.	9213
BATCH NO.	QUAN. IN BATCH	TP	143	LEDGER FOLIO	1200-38-6	SPECIFICATION NO.	
REGISTRATION NO.	MAKE & MODEL	YEAR	1941	TYPE	S.E. TRAINER	MANUFACTURERS NO.	
2855	HARVARD IIA						

2855

HARVARD 2

WASP  
R1340-

100336

2

RCAE REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY AT

DATE

QTO No.

CD No.

TRANSFERS

TRANSFERS

DATE	QTO No.	TO	DATE	QTO No.	TO
31 Aug 56	ATD-873	St Louis Park			
4 Dec 56	<del>D-10-696</del>	<sup>Long 23P 24 May 57</sup> St Lincoln Park			
9 Oct 57	446	St Lincoln Park			
18 Dec 59	846	Spedal Lincoln Park A/F			
18 Oct 60	639	L.A.D. Co.			
		Having been sold to Navis Enterprises (Alberta) Ltd. 11404- 143rd St Edmonton Alta. Sales order 145239 Issue voucher M372 cover			

ME 2305

