

2860

HARVARD II

(WRITE-OFF)

1941

S.E. TRAINER

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS' No.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
11-9-41	A	S. Side Aero. f.d.	1445	#9 SFTSS A659	11/9	LAC. J. Cail	1	Spares produce	
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

12/9/41. Inspection Report from #3 TC recommends that this  
airframe be written off. Flying time 520<sup>10</sup>  
R. Acc 1. - Covered on table striking crash tender and caught fire.  
Total Flying Time - 520<sup>10</sup> hrs (Ault Log Book)

