

2863

HARVARD 11

(WRITE-OFF)

1941

S.E. TRAINER

REGISTRATION NO.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS' NO.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
4-4-41	"C <sub>2</sub> "	Aerodrome Summerside	11600	9SFTS, s 207	4/4	AC.PA. Ballarino			
6-8-41	A	Summerside P.C.P.	1500	9SFTS, s A571	6/8			Spares & produce	
23-6-41	"C4"	S' Side, Aerod.	2300	9SFTS, s A 465	24/6	LAC W. Appleby			
12-5-41	"C2"	Summerside Aerod.	1620	9SFTS, s A 683	12/5	LAC W.D. Whitham			
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Re Acc 3:- 9c spun into earth from 2000 ft altitude while engaged in instrument flying, and burned.  
 Total Flying Time: 330.45 hrs. (Aviation Log Book)

