

2870

HARVARD II

(WRITE-OFF)

1941

S.E. TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURER'S NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N. NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
15.3.43	Time Exp	Boardman Av				28.4.43	# 17.0.
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	# REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
16.11.41	"C2"	Uplands Aerod	1540	2 SFTS, 5642	17/11	LAC Woods			
28.9	"C2"	New Bell Corner Exd	1015	2 SFTS, 54593	29/9	PILO D.D. Anman	1		
16.11	"C2"	Uplands Aerod	1540	2 SFTS, 5642	17/11	LAC Woods			
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re acc. 1 - Pilot was watching back side and turned a/c into a/c 2842.
 22.2.44 - Allotted to # 6 P/O D. Woods to initiate write-off action (after crash)

