

2875

HARVARD II

(WRITE-OFF)

1941

S.E. TRAINER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1.7.41	Crash	Moordwyn				17.9.41	#1.F.C.
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
14/6/41	B	Richibucto N.B.	1300	#95FIS, SA 438	14/6	Lt. J.B. Zduwary		Moordwyn	17/9
7.6	C	Kohler Ave. Id.	2230	#65FIS, SA 138	10/6				
28.11.	C3	Prentiss Road	2000	CFS SA 465	30/11	W.D. Turnbull Solo			
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re Accd: - Forced landed on cross country flight because of bad weather
 8.5.43 Allotted to #6 R.D for Write off action

