

2893

HARVARD II

WHITE-OFF

1941

S E TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	No. IN CREW	DISPOSAL	DATE SERV.
4.4.41	"C"	Summerside P.C. I	1630	95FTS & A253	12/4	LAC C.I. Bucke			
7.7.	"C"	Summerside P.C. I	1200	299115 & A497	7/7	LAC H. Kawener	-		
1.6.42	"A"	Trigon P.E. I	0915	95F753 & E711	11/6	Sgt H. Spinney	1	4RD	
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. acc. 3. Eng inst. 7895/4075. Instructor stated a/c flicked out of loop & he could not regain control. Both bailed out but student's parachute failed & he was killed.

17.6.42 allotted to SAC for salvage and write of action.

