

2906

HARVARD II

1941

S E TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
6.5.43	Time exp.	Mordueys Av.				20.8.43	# 3TC (S.R)
May 42	overhaul	Coir Car + Ody			new 3855 old 1594.55	14.9.48	C. A. C.
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
17.5.41	C7"	Summerside P.C.	2230	957TS A363	19/5	P/O B. Roe.	1		
12.3.42	C3"	Summerside Aerd.	0100	957TS A104	12/3	P/O J. Finley H.R.	1		
16.3.42	C1"	Summerside Aerd.	1820	957TS A110	16/3	P/O J. A. McHugh			
5.5.	C1"	Summerside Aerd.	1130	957TS A184	5/5	P/O DR Dillon			
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re Acci. - Harvards 2906 and 2552 landed in slight cross wind, ground looped damaging ole legs & wing tips

18.9.45 Allotted to No. 6 Repair Depot (A/B) for 2855 inspection & installation

25 Sept 47 - A/B - T.S.D. 3822.55, T.S.D. 1822.40

22 Dec 47 - A/B - T.S.D. 3861, T.S.D. 1561, Condition, Fair, Fitment, Std.

10 Apr 48 - 3895 - 1595

7 March 48 - 3895 - 1595

31 March 49 - A/B - T.S.D. 13985.15, T.S.D. 60.00

of 6 allotted to P.A.R. for model EO 05-55A-6B/14 and 6B/15 (Tail wheel de-clutching and electrical junction Box). Auth. 206 314 d 21 Dec 55. Refray 10/3/58

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D. FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT #3 Training Command DATE 20/2/41 TRANSFER ORDER No. 6248

TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
6.5.43	Woodhouse Av	14/5 T.O. E. 217			
20.8.43	Stored Reserve #3TC	To 3177			
1.9.43	#3TC	To 3458			
2.3.44	Stored Reserve #1TC	To 18943			
6.4.44	#1TC (#168298)	To 12267			
15.1.45	No. 1 A.C.	T.O. 17863 (031)			
18.9.45	WA - No 6 Repair Depot	20 6333			
3/12/45	S.R-MC (4 REMU)	To MC 15675			
1 Oct 46	MC AC (West Cdn)	To MC 12969			
7 May 48	No 115 Sq (Can Cdn & Dly)	To MC 12084			
14 Jun 48	CAC (424 Sqn)	To MC 12364			

REMARKS

R/M. 28/10

U.K. Contribution

24/1/48 feed from North American Aviation
~~Londoner Aircraft~~

10571 12 516

ENGINE TYPE WASP 33H-1 R330-AN-1 UNITS 1 AIR CREW TYPE (CODE) REF. No. 11409

BATCH No. QUAN IN BATCH TP 143 LEDGER/FOLIO 1200-38-6 SPECIFICATION No.

REGISTRATION No. MAKE & MODEL YEAR TYPE MANUFACTURERS No.

2906

HARVARD

1941

S.E. TRAINER

Wichita Model 10

2906

HARVARD 2

WASP
R1340-

2

RCAF REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY AT

DATE

QTO No.

CD No.

TRANSFERS

TRANSFERS

DATE	QTO No.	TO	DATE	QTO No.	TO
14 Sept 48	070-12364	RAC 424 Spdn			
11 Dec 58	882	Sp Lincoln Park			
18 Dec 59	846	Sp Lincoln Park #1			
18 Oct 60	639	L.A.R.L.			
		Having been sold to			
		Davis Enterprises			
		(Alberta) Ltd. 11404-			
		143 rd St Edmonton			
		Alta Sales order			
		145239 Issue			
		voucher M372 core			

ME 2305

