

3022

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
2/7/41	1 "C2"	Dauphin, Man	1245	*10 SFTS s. A45	2/7	P/O W. J. Anderson	1		
5.8.	2 "C21"	Dauphin Aerod.	2345	10 SFTS s. A76	16/8	LAC T. A. Colaninno	2		
23.1.42	1 "C2"	Moncton Aerod.	1030	8 SFTS s. A48	23/1	LAC W. D. Kennedy	1		
12.12.41	2 "C3"	Moncton Aerod.	1630	8 SFTS s. A231	12/12	LAC G. P. Hutchinson	1		
9.4.42	5 "C2"	Moncton Aerod.	2235	8 SFTS s. A302	10/4	LAC G. A. Truvalle	1		
10.6	6 "C2"	Moncton Aerod.	0400	8 SFTS s. A571	10/6	LAC W. Druen	1		
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re acc 4:- Harvard 3022 skidded into Harvard 3762 while taxiing. Eng. installed: Pasp 53H-1 no 9055/4614.
 Re acc 3:- Eng. installed Pasp 53H-1 no Y167/5312

