

3045

HARVARD 11

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
14.8.41	Crash	Woodruff				21.10.41	# ITC.
16.7.41	C crash	Woodruff					
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
6.8.41	B	Field, Slitterville	1520	#2SFTS, & A552	7/8	P/O R.C. Moffat	1	Woodruff	2/10
29.7.41									
9.11.41	3	Prenton Aerod.	1450	C.F.S. & A339	10/11	Sgt L.E. Humphreys	Solo		
13.1.42	4	Prenton Aerod.	1615	C.F.S. & A778	14/1	Sgt C.P. Henning	Solo		
2.2.42	5	Murray Township	1400	C.F.S. & A892	3/2	P.O. R.F. Gill	1		
24.6	6	Camp Borden	0916	157355C128	25/6	Sgt Brittain	1		
7									
8									

D. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re Acc #2 :- Mistake in posting.

Re acc #4 :- Engine installed - Insp S3H-1 no. Y232/5030.

Re acc. 6 :- Ac went into spiral & before recovery was made, wings and fuselage were damaged.

13.5.43 :- "A" crashed "6 Rd" Prenton to submit write-off action immediately.

