

3072

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

| DATE | REASON | DONE BY | REQ'N No. | COST | HOURS SINCE NEW | DATE COMPLETED | ALLOTMENT |
|------|--------|---------|-----------|------|-----------------|----------------|-----------|
| 1 | | | | | | | |
| 2 | | | | | | | |
| 3 | | | | | | | |
| 4 | | | | | | | |
| 5 | | | | | | | |
| 6 | | | | | | | |
| 7 | | | | | | | |
| 8 | | | | | | | |
| 9 | | | | | | | |
| 10 | | | | | | | |
| 11 | | | | | | | |
| 12 | | | | | | | |

ACCIDENT RECORD

| DATE | CATEGORY | PLACE | TIME | REPORT REFERENCE | DATE | RANK & NAME OF PILOT | NO. IN CREW | DISPOSAL | DATE SERV. |
|---------|----------|-----------------------|------|------------------|------|----------------------|-------------|----------|------------|
| 24.2.42 | "A" | 3m N. Otterville Ont. | 1015 | 1459155, A44 | 24/2 | LAC C.H. McCredie | - | Wreck | 24/2 |
| 2 | | | | | | | | | |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |
| 5 | | | | | | | | | |
| 6 | | | | | | | | | |
| 7 | | | | | | | | | |
| 8 | | | | | | | | | |

D. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re acc! This % apparently collided with Harvard 2847 from Dunnville which also crashed near Otterville. Cause of acc. obscure.

