

3198

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
5.12.41	"A"	2m. NE Tilsbury Air	1530	14577S sig.	5/12	PLC. Gorch	1	Write-off	
2									
3									
4									
5									
6									
7									
8									

D. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Reacc. Eng. installed 9596/4726 signal on file 1700-3198, 16178, 850-B-81
 a/c returning to base after formation flying - crashed in bush
 and burnt. pilot and crew killed (LAC R.L. Brockhope Aus.)

