

3202

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
22.6.42	"B" crash	Moorewyn				27.8.42	# 2 JC
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
14.6.42	"B"	Camp Gordon	0130	157255C110	15/6	P/O W J Penrose		Moorewyn	27.8.42
2.8.44	"B"	#11 S.F.T.S		A57	2.8.44				
3									
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Re acc. 1 - Faulty use of brakes when preparing to land caused a/c to turn over.  
 17.8.44: allocated to # 8 (S. L. Lewis) for maintenance & produce

REMARKS:

## RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.
E 135 2/107	2-8-44			#8 R.D.	#8 R.D. (wires)	1-9-44	8-202

## DISPOSAL PARTICULARS

AIRFRAME <i>Spares &amp; Produce</i>	T. O. No. 8-202
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

## AIRCRAFT RECORD CARD

FIRST ENTRY AT # 1 T.C. (#14 S.F.T.S) DATE 26.6.41 TRANSFER ORDER No. 1376

TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
22.6.42	Moordun	T.O. C1.49			
27.8.	# 2 J.C.	T.O. 2525			
3.5.44	Stated Reserve # 2 J.C.	T.O. 12872			
1.6.44	# 2 J.C.	T.O. 13674			
17.8.44	# 8 R.D. (wires) 7pg (4/4)	T.O. D 453			
1.9.44	Spares & Produce	T.O. 8-202			

REMARKS

ENGINE TYPE WASP S3H-1 UNITS 11 AIRSCREW TYPE (CODE) REF. No.

BATCH No. QUAN. IN BATCH TP 7 LEDGER FOLIO 1200-38-4 SPECIFICATION No.

REGISTRATION No. 3202 MAKE &amp; MODEL HARVARD II (WRITE-OFF) YEAR 1941 TYPE S E TRAINER MANUFACTURERS No.