

3216

HARVARD 11 A

1941

S E TRAINER

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
23.7.42	"B" Crash	Woodruff et al				29.10.42	#170 (SR)
6 May 48	See remark	Can. Can. D. By	CDW 1392		3202.45 2374.50	21 June 48	1/11:00
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
2.9.41	"C"	Camp Borden Ont.	1445	145715 s A29	2/9	LAC T.G. Reid			
20.9	"C4"	Oylmer. Que.	1040	145715 s A55	20/9	LAC F.W. Mough	1		
3									
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

28.8.47. inter-communication installation only 6 hrs.  
 21.6. 77689 cost 500.1.3.  
 aft home - 2275.35; condition good  
 6 Apr. 48 aft home - 2275.35; condition good, 2 hrs. of 1st  
 4 Dec. 48 aft home - 3202.45; 2274.50; Do for preparation for flying to  
 contractors  
 6 May 48. For reconditioning & modification to spec RTR-1.7  
 31 Mar 49 - aft home - 2381.10. 750. 104.55  
 aft allotted to PARR for make FO 05-55A-6B/14 & 6B/15 (tail wheel delecting  
 and electrical junctions base), with LOG 314 21 Dec 55. 6 PART 526 4 May 56





