

3230

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
29.4.43	crash	Woodys Av.				10.6.43	#1 T.C. (S.R.)
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
20.5.43		Uplands Aerod	1400	287255A789	20/5	Lt. J.C. Bowring			
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. acc. 1 - Pilot failed to observe Stationary Gc Harvard 2644 and taxied into it. No damage done to Gc 3230.

25.4.44. Involved in A crash allotted 6 H.P. for salvage feeding instructions

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.
#68958 E107 E135	2.5.44	103889(3230)		#6.P.O.	#6.P.O.(WR)	28.6.44	6-136

DISPOSAL PARTICULARS

AIRFRAME <i>spares & Produce</i>	T. O. No. 6-136.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
8.12.41	" 3 T.C.	28/11 T.O 12523			
29.4.43	Woodhouse Ave	11/16 T.O. E. 163			
10.6.43	Stored Reserve #1 T.C.	12/10 T.O. 1515			
14.7.	#1 T.C.	10/19 T.O 2196			
25.4.44	#6 Repair Depot (WR)	T.O E174			
28.6.44.	Spares & Produce	T.O 6-136.			

REMARKS

ENGINE TYPE WASP S3H-1	UNITS	AIRSCREW TYPE (CODE)	REF. No.
BATCH No.	QUAN. IN BATCH TP 7	LEDGER FOLIO 1200-38-4	SPECIFICATION No.
REGISTRATION No. 3230	MAKE & MODEL HARVARD II (WRITE-OFF)	YEAR 1941	TYPE S E TRAINER
MANUFACTURERS No.			