

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	No. IN CREW	DISPOSAL	DATE SERV.
8.9.41	"C"	Pictou aersd.	1205	CTS. sig A 133	8/9	20. B.W. Windsor	1		
23.11.	"A"	2m NW Pictou A.	0300	CTS sig A 197	23/11	P.O. L.C. Barkman		Wrecked	1941

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. acc. 2 During night flying "C" cut swath through apple trees, ending up against large tree - Engine rolled 350 feet beyond fuselage and wings completely separated. (Pilot lost control of "C")
 Engine rolled 350 feet beyond. Pilot slightly injured.
 Engine installed 9641 / 4771

