

3772

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
5-6-41	A	Dauphin Man	2325	#10SFTS, s A28	6/6	IACRA Alexander		WRITE-OFF	
17-11	C3	St. Hubert Road	2100	13SFTS, s A58	18/11	1st Lt. Stanford	Lolo		
3									
4									
5									
6									
7									
8									

D. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re Acc: - 9c spiralled into ground Eng install. 9038/4597
 The date of accident and time is amended to read 6/6/41,
 0025 hours, instead of 5/6/41, 2325 hours, as reported
 by their signal A 28 6/6 - ref. 10591S sig. A29
 Re acc 2 - Sig AT62, 3TC, report 9c 3713 as 9c involved in this crash.

