

3778

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
30.10.41	"B2"	Wplando Aerod.	0900	25FTS 5A619	30/10	Lt. J. S. Adams	—		
29.12.	"C1"	Wplando Aerod.	1630	25FTS 5A670	30/12	P/O J. C. Lee	1		
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

The acc. 2: Harvard 2872 struck a/c 3778 on passing on take off
 Engine installed - Deasp S3H-1 no. 9329/1470

