

3790

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
12.5.43		Woodruff Av.				24.6.43	#3 TC(SR)
23.8.	Crash	Woodruff Av.				29.9.43	#1 TC(SR)
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
23.8.41	"C10"	Dunham Man	1440	"105975 3A84	25/8	LAC ARN McFadden	1		
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Repair of 3017 carried into 3790  
 23. 8. 43. Allotted to Woodruff Aviation for re conditioning after crash.

## REMARKS:

Completely destroyed by fire at #1 S. F. T.S. Camp Boden 9/12/43

## RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.
4/TCO E.109	9.12.43	938-1-8 971-16-1 HV2	25.4.44			28.8.44	15787

## DISPOSAL PARTICULARS

AIRFRAME	Written off	T. O. No.	15787
ENGINE/S (QUOTE SERIAL NOS.)		T. O. No.	
AIRSCREW/S (QUOTE SERIAL NOS.)			
ACCESSORIES			
REMARKS:		EFFECTIVE DATE WRITTEN-OFF	

## AIRCRAFT RECORD CARD

FIRST ENTRY AT #2 TC Winnipeg DATE 29.4.41 TRANSFER ORDER No. 459

## TRANSFERS

## TRANSFERS

DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
23.9.41	#3 TC	#13 S.F.T.S.	T.O.	2929	
12.5.43	Northrup Av.	#5	T.O.F	258	
24.6.	Stock Reserve #3 TC	#26/6	T.O	1789	
6.7.43	#3 TC		To	2029	
23.8.43	Northrup Av.		T.O.	E.1021	
29.9.	Stock Reserve #1 TC		T.O	4191	
1.12.	#1 TC		T.O	5622	
28.8.44	Write-off		To	15787	

REMARKS

ENGINE TYPE WASP S3H-1 UNITS | AIRSCREW TYPE (CODE) REF. No.

BATCH No. QUAN. IN BATCH TP 143 LEDGER FOLIO 1200-38-6 SPECIFICATION No.

REGISTRATION No.	MAKE & MODEL	YEAR	TYPE	MANUFACTURERS No.
3790	HARVARD II (WRITE-OFF)	1941	SE TRAINER	