

3815

HARVARD II

1941

S E TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURER'S NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
20.10.43	reconditioning	Noorduyn Aviation				13 544	SB. 1 TC
17 Aug 50	mod - open R.M. 1-7	L.C. Ady	20501660 20501661			16-1-51	2L
27 Dec 50	investigating malfunction	C.C. Ady				26-7-51	ADC
27 Nov 56	reconditioning to spec R. 1-4	A.P.C.	572862				
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
2.10.41	1 "C1"	Wicksteed Aerod	2250	11SEISS A203	3/10	Lac R. Hamilton			
19.5.42	2 "C2"	Wicksteed Aerod	2155	1457255A 123	20/5	Lac B.S. Roberts			
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re acc 1 - a/c 3820 and 3815 taxied into each other.

18.9.45 Allotted to No. 6 R.O. (at Res) for A.T.R. II installation.

12 May 47 - Ltd. sp. 1138 pg. on 1038 B6-2-B. T.S. 71.35 49.25; T.S. 0. 871.30.

6 Nov 47 - 24-6. 7189 d 28 Aug 47 on 500. 1-3. A.T.R. II and A.R.P.S. installation complete.

1 Jan 48 - A/c sp. T.S. 71.35 39.25; T.S. 0. 871.30. Condition Good.

6 Dec 51 - A/c sp. fitted with gyro gyroscope - Rad 2501661
T.C. 2564d 30 Jan

REMARKS:

RECORD OF WRITE-OFF

APPLICATION REC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT #2 T.C. Winnipeg		DATE 5/5/41	TRANSFER ORDER No. 559		
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
20.10.42	#3 T.C.	T.O. 13544	27 June 41	No. 11 TSU (C. E. F. J. J.)	TO 1193
3.3.	#1 T.C.	T.O. 14945	26 June 41	AFC	TO 1263
	#14 SFTS		26 June 41	In the No. 11470227 My	OTO 1129
20.10.43	Noorduyn Aviation	T.O. C. 1872			
13.5.44	Stored Reserve #1 T.C.	TO 13196	9/12/43	SR6 RD	OTO 1724
17.5.44	#1 T.C. (#20 E.F.T.S.)	T.O. 18899	22 Nov 46	11 TSU AIC C. E. F. J. J.	TO 636
16.11.44	Stored Reserve #1 T.C.	TO 17141			
15.1.45	Stored Reserve #1 a.c.	T.O. 17863 (C35)			
3.2.45	a.c.	TO 18349			
18.9.45	U.S. No. 6 Repair Depot	TO 2333			
3/12/45	S.R. MC (48 E.F.T.S.)	TO MC 15675			
17 Aug 50	No. 11 TSU (C. E. F. J. J.)	TO 1209			
16 Jan 51	26 (Denton)	TO 1497			

REMARKS:

Ref No. 38/40

U.K. Contribution

5/5/41 - Rec'd from North American Aviation

ENGINE TYPE WASP 83H-1	UNITS 1	AIRSCREW TYPE (CODE)	REF. No.
BATCH No. QUAN IN BATCH TP 143	LEDGER FOLIO 1200-38-6	SPECIFICATION No.	
REGISTRATION No. 3815	MAKE & MODEL HARVARD II A	YEAR 1941	TYPE S.E. TRAINER
			MANUFACTURERS No. Under ATU

OVERHAUL DATA

DATE	QTO No.	CONTRACTOR	REPAIRS
28 Mar 57	Log 275	CD 572862	Insulating