

3821

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION NO.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS NO.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
16/6/41	"A"	Yorkton, Sask.	0015	#115ETS, SM85	15/6	LAC L. W. Blair	-	spare parts produce	
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Re Acc. - ac went into gentle spiral dive into ground during night flying. Accident took place 1 mile south of Studia aerodrome - pilot killed.

