

AJ 761

HARVARD II

(WRITE-OFF)

1941

S E TRAINER

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
22/1/42	"A"	Medicine Hat A	1125	34SFTS SA58A	22/11	P. R. G. Blomires	1	Spares produce	
22/2/42	C14	Medicine Hat A	1305	34SFTS ST85	22/12	P. R. G. Blomires	1		
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re Acc 2: Harvard A1761 swung on takeoff and hit stationary
 Harvard A1828. Col. P. R. Walth, pupil pilot seriously
 injured. Pilot slightly injured.

Re Acc. 1: Engine installed - Hosp 834-1 no. 11442/213723.

