

AJ 828

HARVARD II

(WRITE-OFF)

1941

S.E. TRAINER

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1	Crash				271.55		Write-off
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
22.1.42	A	Medicine Hat, Almd	1125	34 SFTS SA559	22/1	Pvt. G. Hoar	1	Spares & produce	
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Re acc. 1: Harvard A1761 swung on takeoff and hit stationary Harvard A1828. Pupil pilot Lt. Eric Thomas Markham and Pilot Hoar killed.  
 Engine installed - Insp S3H-1 no 89979/213343.

