

| | | | | |
|------------------|--------------|------|------|-------------------|
| BW 629 | HUDSON III | RA | 1942 | TE BOMBER |
| REGISTRATION No. | MAKE & MODEL | YEAR | TYPE | MANUFACTURERS No. |

OVERHAUL DATA

| DATE | REASON | DONE BY | REQ'N No. | COST | HOURS SINCE NEW | DATE COMPLETED | ALLOTMENT |
|------|--------|---------|-----------|------|-----------------|----------------|-----------|
| 1 | | | | | | | |
| 2 | | | | | | | |
| 3 | | | | | | | |
| 4 | | | | | | | |
| 5 | | | | | | | |
| 6 | | | | | | | |
| 7 | | | | | | | |
| 8 | | | | | | | |
| 9 | | | | | | | |
| 10 | | | | | | | |
| 11 | | | | | | | |
| 12 | | | | | | | |

ACCIDENT RECORD

| DATE | CATEGORY | PLACE | TIME | REPORT REFERENCE | DATE | RANK & NAME OF PILOT | NO. IN CREW | DISPOSAL | DATE SERV. |
|-------|----------|-----------------|------|------------------|------|----------------------|-------------|----------|------------|
| 22.43 | B | Yarmouth Aerod. | 1010 | 113 Sqdn's A57 | 2/2 | Hob. Draper | 2 | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re Acc. 1:- Eng. inst. 39556/211272, 39527,
 ac swerved on take-off and hit snow bank.
 8.8.44:- Allotted 1 T.C. for Con. to Transport Dept & use of visiting Fl. Trenton.

