

BW 542	HUDSON III	<i>5012</i>	1942	T E BOMBER	
REGISTRATION No.	MAKE & MODEL	YEAR	TYPE	MANUFACTURERS No.	

**OVERHAUL DATA**

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
3.8.42	Crash 'B'	Clark Ruse				25.9.42	E.A.G.
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

**ACCIDENT RECORD**

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
25.7.42	"B"	Dartmouth N.S.	1758	W.B. Gen. A98	25/7	P/O V. E. Hill	3	C. Ruse	25.9.42
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

**AIRCRAFT RECORD CARD**

PAT'D 1920

**REMARKS**

*Re. Acc. 1. Equip. inst. 39592/211308. 39581/211297. Swung when landing after patrol and left elec. leg gone away.*

