

FM122

LANCASTER X (LANDPLANE)

1945

M E BOMBER

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1	Photo	awke				15/6/50	ATC
15 Dec 53	2 contrast beam	Do. Han	CD W376818				
19 Dec 53	3 c.i.	Do. Han	CD W376818				
4 Feb 55	5A fuel tanks replacements	11 TSU (Jimmy D.)	576818			25 Feb 54	ATU
23 Feb 56	5 for preparation of substructure of collection surveys up to date with 6 parts list in all repairs	Jimmy A	376818			23 Feb 56	ATC
7	7 authorized						
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
1									
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

REMARKS:

## RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

## DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

R.C.A.F. E. 258B — 1M-1.43 (8029) H.Q. 865 — E-233

## AIRCRAFT RECORD CARD

FIRST ENTRY AT	E.A.C.	DATE	28/6/45	TRANSFER ORDER No.	18504
----------------	--------	------	---------	--------------------	-------

TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
10.1.46	12 AIR (AV. Roc (Canada) Ltd)	T.O. MC 16061			
28 Dec 46	1 (E) (A. U. Roe)	T.O. MC 13240			
15 June 50	ATC (408 P Sgt)	T.O. - 1129			
15 Dec 53	12 TS U (De Han) 29673 d 17 Dec 53	OTC - 1752			
18 Dec 53	12 TS U (De Han)	OTC - 1770			
25 Dec 54	ATC (408 Sgt)	OTC - 1969			
4 Feb 55	11 TS U (Training A) Cb	OTC - 421			
4 Feb 55	ATC (408 Sgt) Rock	OTC - 421			
28 Feb 56	11 TS U (Training A) Cb	OTC - 741			
23 Feb 56	408 Sgt Rockcliffe	OTC - 741			
27 Feb 56	408 Sgt Rockcliffe	OTC - 741			
27 Feb 56	408 Sgt Rockcliffe	OTC - 741			

REMARKS:

Handed over from mutual aid with memo 1039EA-1-8 (550/51) d. 17.1.46  
 28/6/45 - THIS AIRCRAFT RECEIVED FROM No. 6 (BR) GROUP OVERSEAS.

4-0 344966  
 71-1 346077  
 9-1 346077  
 346057  
 22415 239-0 344760  
 391-1 346077  
 39-1 345352  
 129-0 346057  
 Can. Equip't.

ENGINE TYPE	MERLIN 224	UNITS	4	AIRSCREW TYPE (CODE)		REF. No.	
BATCH NO.	QUAN. IN BATCH	LEDGER FOLIO		SPECIFICATION No.			
REGISTRATION NO.	MAKE & MODEL	YEAR		TYPE		MANUFACTURERS No.	
FM122	LANCASTER X P (LANDPLANE) BR60	1945		M.E. BOMBER		8-113918	



OVERHAUL DATA

DATE	QTO No.	CONTRACTOR	REPAIRS
26 June 59	378	UTSU 772816	for work outlined in letter 1038EA-3 (LC/RD) 22 June to UTSU
# June 62	364	<del>Crescent</del> Granville Heating 179818	direct structural fatigue & corrosion