

FM199

LANCASTER X P

M. E. BR. LANDPLANE

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1	Photo Mod	A. V. Kae					
2.6.52	Repair for start and break change	Ad Pox	511965			2.6.52	ATC
15 Dec 53	bracket loss	De Dow	376818			17 Feb 54	ATC
30 Mar 54	Repair	Fairley A	376818			30 Mar 54	ATC
14 May 54	Repair on fly-in basis for preparation + sub	Fairley A	376818			14 May 54	ATC
23 Feb 56	minor inspection on wing fuel apt. with cost left in hand material of fuel AN/ARN - 6 in accordance with FAC FL 99 to include repairs as per Fairley A	Fairley A	376818			23 Feb 56	ATC
15 R 5 Jan 56	for rail bumper fuel tank change in engine motor inspection equipment	Fairley A	572820				

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
1									
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

1 for photo modification A.V. Kae - Q1452 - 17 Dec 46  
 on 10/38 EA-1-8.

23 Aug 48 - FS M - 53.10, attached to E. G. K. in accordance with AD 105  
 Directive 13-48, covering installation of air conditioned  
 camera compartment.

1 Apr 49 - a day FS M - 134.05, FS M A

REMARKS:

## RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

## DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

R.C.A.F. E. 233D 5M-1-44 (3801) H.Q. 895 E-299 - K.P. 99359

## AIRCRAFT RECORD CARD

FIRST ENTRY AT *MC #1 GPO (A.V. Roy)* DATE *21 Aug 46* TRANSFER ORDER No. *MC 12685*

TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
<i>23 Aug 48</i>	<i>A.J.C. (E &amp; E)</i>	<i>To. MC 1229</i>	<i>4 Jul 56</i>	<i>107 Flying A Squadron</i>	<i>QTO 713</i>
<i>2 Apr 52</i>	<i>12TSU (A/C Pa)</i>	<i>QTO 1172</i>	<i>4 Jul 56</i>	<i>408 Squadron Rockcliff</i>	<i>QTO 713</i>
<i>2 June 52</i>	<i>ATC (Rockcliff)</i>	<i>QTO 1173</i>	<i>20 Oct 56</i>	<i>100 R to R</i>	<i>QTO 565</i>
<i>15 Dec 53</i>	<i>12TSU (De Nav)</i>	<i>QTO-1752</i>	<i>30 Dec 56</i>	<i>Serviceable Personnel (RD)</i>	<i>QTO 565</i>
<i>17 Feb 54</i>	<i>ATC (408 sqd)</i>	<i>QTO-1937</i>			
<i>30 Mar 54</i>	<i>11TSU (Fairfax)</i>	<i>QTO-1065</i>			
<i>30 Mar 54</i>	<i>ATC (208 sqd)</i>	<i>QTO-1065</i>			
<i>14 May 54</i>	<i>11TSU (Fairfax)</i>	<i>QTO-1136</i>			
<i>14 May 54</i>	<i>ATC (408 sqd)</i>	<i>QTO-1136</i>			
<del><i>14 May 54</i></del>	<del><i>ATC (408 sqd)</i></del>	<del><i>QTO-1136</i></del>			
<i>23 Jul 56</i>	<i>11TSU (Flying A) Bb</i>	<i>QTO-741</i>			
<i>23 Jul 56</i>	<i>408 sqd Rockcliff</i>	<i>QTO-741</i>			

REMARKS:

*21 Aug 46: Received from the Mutual Aid Board*

<i>346052</i>	<i>95-1</i>	<i>243-0</i>	<i>346210</i>	<i>22415-3-0</i>	<i>V 345007</i>
<i>346199</i>	<i>204-1</i>	<i>204-1</i>	<i>346014</i>	<i>22415-10-1</i>	<i>V 345998</i>
<i>345429</i>	<i>243-0</i>	<i>95-1</i>	<i>346199</i>	<i>22415-95-1</i>	<i>V 346042</i>
<i>346210</i>	<i>244-3</i>	<i>294-0</i>	<i>346052</i>	<i>22415-27-0</i>	<i>V 346109</i>

ENGINE TYPE	<i>Merlin 224</i>	UNITS	AIRSCREW TYPE (CODE)	REF. No.
BATCH No.	QUAN. IN BATCH	LEDGER FOLIO	SPECIFICATION No.	
REGISTRATION No.	MAKE & MODEL	YEAR	TYPE	MANUFACTURERS No.
<i>FM199</i>	<i>LANCASTER X P</i>	<i>ARC 6 RD</i>	<i>✓</i>	<i>M.E. BR. LANDPLANE</i>
				<i>Cont</i>



