

OVERHAUL DATA							
DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1					1162.25		
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD									
DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
5/6/41	1 "C10"	Lethbridge, Alta.	1800	5 EFTS, sT266	6/16	1/Lt. B. M. Lean	1		
12/1/42	2 "A"	High River, Altd.	1315	5 EFTS sT. 1	13/1	Pilot Arnold R.S.	Solo	Spares + Producers	
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. Acc. 2 :- Eng. installed 85573/7761
 Pilot made bad landing during gusty wind, ballooned
 to 100 feet and dived into ground during time. 1162.25 hrs.
 from Inspection Report 7.2.42.

