

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
9.10.41	"A"	Malton Aerod.	1025	IEFTS SA 71	9/10	CAC R. A. Swall	Solo		
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. Acc. 1:- Eng. installed # 87198/7378. Aircraft bursted on crashing. Pilot noticing aileron control was not functioning properly decided to land when passing over aerodrome. At 2000 ft. discovered he had no aileron control & went into d/c. Pilot parachuted safely.

Total Flying Time:- 547 ⁴⁵ hrs (auth "ITC letter, 926-22-1, d/22/9/42)

