

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
TECH.	DISOB.	NEG/ICE	INEXP/ICE	MISCEL.	INSTRUCT.	FLI CONTR.	OTHERS	PRIMARY	FL CONTS.	MOV. SURFS.	STAB. SURFS.	W. STRUTS	LAND GEAR	FLOATS	FUSE OR HULL	TAIL SKID OR W.	ENGINE MOUNT.	MISCEL.	UND/TD	PRIMARY	FUEL SYS.	COOL SYS	IGNIT SYS.	LUB N SYS.	ENG STR.	AIRCREW A.	ENG CONTS.	MISCEL.	UND/TD	PRIMARY	
PILOT		OTHERS								AIRFRAME FAILURE										ENGINE FAILURE											
CAUSES OF ACCIDENTS																															
UNIT # 8 S.F.T.S.		COM.		PLACE		DATE 21-8-41		TIME 23:00																							
Moncton, N.B.		3		Moncton, N.B.		H.Q. FILE 1100-63-73																									
A/C TYPE		Anson		No. 6373 D		CRASH CAT. C 9		SE		ME X		DAY		NIGHT X																	
Anson				6363		C 7				X				X																	
NAME		RANK		No.		DUTY		INJURIES								SERIOUS															
Minturn, F.L.		6373 D		LAC		R66336		P.		Uninjured								FATAL		INJURY											
Gray, J.O.		6343		LAC		R83075		P.		Uninjured																					
																		CARD SERIAL NO.													
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																			
Anson		6373		Serious								INST. NIGHT		ON TYPE				TOTAL		LAST 6 MOS											
Anson		6363		Serious		MINTURN		-----		17 4		33 29				59 60															
Cheetah(2)				NIL		GRAY		-----		16 2		31 47				61 73															
Cheetah(2)				NIL																											
SIGNAL No. & DATE		UNIT No. & DATE				COM. No. & DATE				REPORT				FILE				DATE													
A 637 22-8-41																															
NATURE OF ACCIDENT																															

CAUSES
 MISCELLANEOUS
 FLIGHT
 STAGE OF

UN/D
 PRIMARY
 HAND Q
 INSTS.
 WEATHER
 DRINKS.
 AL G SURF.
 OTHER
 UN/D
 PRIMARY
 TAXIING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ
 3RD.
 INJURY
 RAT

) DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

) Nightflying. Taxiing.

OR COMMANDING OFFICER'S REPORT:

) NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

MONTHLY ACCIDENT RETURN.

) Pilot of 6373 failed to see aircraft
) 6363 parked on runway and collided
) with it, damaging starboard wing of
) 6373 and port wing of 6363.

COMPOSITION:

Muller
1-1-68
TCN/it

RECOMMENDATIONS:

) PRIMARY CAUSE:

) Failure on part of pilot of 6373
) to see aircraft 6363 parked on
) runway.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

DISCIPLINARY ACTION:

PILOT FORFEITS 14 DAYS PAY; 7 DAYS C.B.

LOG BOOK ENDORSED.

) SECONDARY CAUSE OR CONTRIBUTING FACTORS:

) AIRCRAFT 6373 COLLIDED WITH AIRCRAFT 6363.

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____