

<i>)</i> (1)	DUTY ON WHICH ENGAGED: FLYING TRAINING. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Alechaet swund on take-off, and ground looped.	COURT OF INQUIRY, INVESTIGATING OFFICER'S REPORT: R 170	CER)
)		RECOMMENDATIONS:)))
	PRIMARY CAUSE:)
	AIRCRAFT HIT BUMP ON TAKEOFF)
)		ACTION TAKEN: (A) Disciplinary (B) Tachwical (C)	Отнеч)
50 00.		Instructor's flying technic checked by Chief Instructor)
	SECONDARY CAUSE OR CONTRIBUTING FACTORS:))
	GROUND LOOP		RECORDED BY DATE)
			CHECKED BY DATE))))))))))