



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Practising sequences 6-7-8-9-12-16-17 OR COMMANDING OFFICER'S REPORT:

Monthly Accident Return.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

LH/PSHH

Pupil landed on wheels well up the field bounced slightly, control column put forward and back a/c kept bouncing from one wheel to the other with tail going up and down until one wing touched with tail up causing the a/c to turn and go over PRIMARY CAUSE: on its back.

RECOMMENDATIONS:

Pilot error. Bounced aircraft on landing with no correction made.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Further instruction to be given on opening throttle after bouncing aircraft. LAC Donagani under Medical supervision.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Aircraft continued to bounce touch the ground with wing tips and went over onto its back breaking airscrew and rudder.

RECORDED BY

DATE

CHECKED BY

DATE