

CASPIR Aircraft Accident Cards

Serial: AR756

Title: Airspeed Oxford Mk. I serial:AR756 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1941-August-13. Oxford s/n AR756. This accident involved 1 person. Coulson JB

Keywords: RAFOxford ,AR756,34 SFTS,34 Service Flying Training School,Aerodrome,1941-August-13,CoulsonRCAF L20

Created: 1941-08-13

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AR756>

DUTY ON WHICH ENGAGED:

Solo Flying

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Monthly Accident Return.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft flew into ground whilst landing in a strong wind.

DATE:

COMPOSITION:

L.H. P. 1944

RECOMMENDATIONS:

PRIMARY CAUSE:

Error of judgement by pilot. He was frightened when he saw Aircraft AR921 turn in front of him.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Disciplinary action taken against F/O Mellor flying Oxford AR921. The pilot turned to close from aerodrome.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Pupil failing to check approach angle before hitting the ground.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____