

DUTY ON WHICH ENGAGED:

Solo Practice sequences 10-16-22.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Engine failure due to icing.
Student overshoot landing field
hitting wire fence.

RECOMMENDATIONS:

PRIMARY CAUSE:

Error in judgment on the part of
the pupil in that he overshoot
landing field.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

HIT WIRE FENCE

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____