

Precautionary landings.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:	
	R 170	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:  Collided with gas roller while taxing damaging wing.	DATE: COMPOSITION:	
	RECOMMENDATIONS:	•
PRIMARY CAUSE:	N11	
Failed to see gas roller while taxiing. Carelessness.		
	ACTION TAKEN:  (A) Disciplinary (B) Technical (C) Other	
	Log Book endorsed "Carelessness"	
SECONDARY CAUSE OR CONTRIBUTING FACTORS		
Failed to see Gas Roller while To		