

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	)
Circuits and landings at night	OR COMMANDING OFFICER'S REPORT:	)
NATURE OF ACCIDENT AND STAGE OF FLIGHT:  Right tire blew on landing pro- bably caused by previous heavy landing.	DATE: COMPOSITION:  R 170  COMPOSITION:	) )
<b>4</b> 00	RECOMMENDATIONS:	( (
PRIMARY CAUSE:	Nil	
Fire Blew after heavy landing resulting in swing which damaged Ole leg and wheel.	O  ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	)
	Pilot interviewed and admonished by Squadron Commander.	)
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		,
Pilot stopped result of swing to r	ight RECORDED BY DATE	1
by the use of left rudder and bra	ke	
right by the use of left rudder an wheel were damaged	d brake right oleo leg and CHECKED BY DATE	) )