

))))))
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
Night circuit and landings. NATURE OF ACCIDENT AND STAGE OF FLIGHT:	OR COMMANDING OFFICER'S REPORT: RI70	1
) STUDENT PILOT CAME IN FOR A NORMAL LANDING. HE CLOSED THE THROTTLE ABOUT TWO FEET ABOVE THE GROUND, AND THEN SUDDENLY MOVED THE CONTRO COLUMN BACK VERY RAPIDLY CAUSING THE AIRCRAFT		
) TO STALL AND FLICK, DAMAGING THE PORT WING.	RECOMMENDATIONS:	
)	NIL	
) PRIMARY CAUSE:		
) AIRCRAFT STALLED ABOUT TEN FEET ABOVE THE GROUP) AND FLICKED.	ND .	
)	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
))	More Instruction Being Given.	
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
THE PORT WING HIT THE RUNWAY.	RECORDED BY	DATE
)	CHECKED BY	DATE
)		