> /			&					CEL. JUDO	ELMARY (JUL)						
	PILOT	OTHERS		AIRF	RAME		CCIDE	NTS	<u> </u>	ENGI	NE F	AIL	URE		?/ ,
P.E. OF	UNIT # 1 8	F.T. B.	COM.	PLACE			ONTARIO.		DATE H.Q. F	24-11-	41 TI	IME 2	239	1 1 / .6	n' /
	A/C TYPE HARY			No,	2677		CRASH CAT. ₩C±	н	SE X	ME	DA	Y	NIGHT X	S MER	5/
/م 		NAME	F	RANK	No.	DUTY	1	טנא	RIES			SERI	ous		JE /
		MAN, T.H.		SGT. RE		P		INJURE			FA	ATAL	INJURY	E Z	7 7
OF ENGINE				MANUFACTOR OF THE STATE OF THE							5	CAF SERIA		EOUS CHAIR	
TY PE	TYPE A/F No EXTENT			REPORT	SERIAL	DATE HO			DURS FLOWN BY PILO			TS		1 1 / 6	N/
2	& ENGINE HARVARD	No. 2677	OF DAMAGE SLIGHT		No.	DAI	- 11	NIGHT	ON T	YPE solo	TOT.		LAST 6 MOS		-/-/
GORY	Waso	7173	SLIGHT				31	83							\ \$/
SATEGO	SIGNAL NO.	& DATE	UNIT NO. & C	DATE	сом.	No. & C	ATE	REPO	RT	FIL	E.	D	ATE		4 ky 38

) DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFI	CER)
NIGHT CIRCUITS AND LANDINGS.	ON COMMANDING OFFICER'S REPORT:	P170	V)
) NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:)
) ENGINE FAILURE AT THE HEIGHT OF APPROXIMATELY	COMPOSITION: COMPANIEN	182144/2)
20 FEET FOLLOWING A TAKEOFF. LANDED AIRCRAFT				· ·
IN THE SNOW, GOING UP ON ITS NOSE AS LANDING RUN				,
) HAS COMPLETED.	RECOMMENDATIONS:)
· ·	NIL			ŕ
) PRIMARY CAUSE:	2			
) ENGINE FAILURE.)
))	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Otto	HER))
	NIL)
))
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
AIRCRAFT NOSED UP IN SOFT GROUND ON FORCED LANDING.		RECORDED BY	DATE)
))	·	CHECKED BY	DATE)
)))))