

DUTY ON WHICH ENGAGED: Take offs and landings NATURE OF ACCIDENT AND STAGE OF FLIGHT: Taxied off runway onto taxi strip stopped to raise flaps - starboard wing struck by Harvard 2556 piloted by LAC Goodbrand, W.A.	COURT OF INCLUDY INVESTIGATION AND	MO27) R170	, , , ,
Carelessness on part of pupil pilot LAC Goodbrand - no blame attached to LAC Burns, pilot of 2696 ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER L.A.C. Goodbrand awarded 7 days C.B. and log book endorsed as Carelessness.			
Port wing of Harvard 2556 struck starboard wing of Harvard 2696, the causing demagn to alleron of Harvard 2696.	-	RECORDED BY CHECKED BY	DATE .