

## CASPIR Aircraft Accident Cards

---

**Serial:** AS268

**Title:** Airspeed Oxford Mk. II serial:AS268 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1941-December-02. Oxford s/n AS268. This accident involved 4 people. Buchanan FM, Lancaster TR, Lazenby CH, Lenten DF

**Keywords:** RAFOxford ,AS268,35 SFTS,35 Service Flying Training School,Hanna Alberta,1941-December-02,Buchanan,Lancaster,Lazenby,LentenRCAF L20

**Created:** 1941-12-02

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS268>



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

**Communication Flight to No.4  
T.C., Calgary.**

OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

*1/21/52*

**Precautionary landing with under-  
carriage retracted owing to in-  
clement weather.**

RECOMMENDATIONS:

**Nil**

PRIMARY CAUSE:

**Inclement weather.**

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

**Pilots log book endorsed.**

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

**Error in judgment on part of pilot  
in landing with undercarriage retracted.**

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_