

32	JUL.	31	TECH.	30	DISOB.	29	NEG NCE	28	INEXP NCE	27	MISCEL.	26	INSTRUCT.	25	FLT. CONTR.	24	OTHERS	23	PRIMARY	22	FL. CONTRS.	21	MOV. SURFS.	20	STAB. SURFS.	19	W. STRUTS	18	LAND GEAR	17	FLOATS	16	FUSE. OR HULL	15	TAIL SKID OR W.	14	ENGINE MOUNT.	13	MISCEL.	12	UND TD	11	PRIMARY	10	FUEL SYS.	9	COOL SYS.	8	IGNIT. SYS.	7	LUB'N SYS.	6	ENG. STR.	5	AIRSCREW A.	4	ENG. CONTRS.	3	MISCEL.	2	UND TD	1	PRIMARY	19	HAND G.	18	INSTS.	17	WEATHER	16	DRKNS.	15	ALG SURF.	14	OTHER	13	UND TD	12	PRIMARY	11	TAXIING	10	LANDING	9	FLIGHT	8	TAKEOFF	7	FLIGHT	6	STATRY	5	FATAL	4	INJ.	3	3RD.	2	INJURY	1	INJURY
AC		TYPE OF ACCIDENT		PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																																																																																			
CAUSES OF ACCIDENTS		PLACE		DATE		TIME																																																																																															
C.T.S.		Rockcliffe, Ontario		12-1-42		1030																																																																																															
A/C TYPE		No.		CRASH CAT.		H.Q. FILE																																																																																															
Battle Goblin		R7374 NR335		Nil C 5		1100-3-35																																																																																															
NAME			RANK		No.		DUTY		INJURIES				SERIOUS																																																																																								
Henderson, E.			F/L		C2635		P.		Uninjured				FATAL INJURY																																																																																								
Byrne, E.W.			P/O		J5809		P		Uninjured																																																																																												
Plew, W.R.			Sgt.		R83205		SP		Uninjured																																																																																												
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																																																																									
Battle		R7374		Unknown								INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS																																																																																			
Goblin		NR335		Serious								5 Nil		Nil 7		15 525																																																																																					
SIGNAL No. & DATE				UNIT No. & DATE				COM. No. & DATE				REPORT		FILE		DATE																																																																																					
A 244 13-1-42																																																																																																					
CATEGORY		TYPE OF ENGINE		NATURE OF ACCIDENT																																																																																																	

DUTY ON WHICH ENGAGED:

Practice flying.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Battle 7374 collided with Grummon
Goblin while taxiing - rudder of
Goblin damaged and replacement
needed.

DATE:

COMPOSITION:

11/27/47
TCVP
TCVP

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Gross carelessness on part of pilot
of Battle - claims he did not see
Goblin.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

9. Collision

The incident was reported to the officer Commanding
the Unit to which P/O Byrne belonged.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Battle 7374 collided with Grummon
Goblin while taxiing.~~

RECORDED BY

DATE

CHECKED BY

DATE