

TYPE OF A/C		PILOT		OTHERS		AIRFRAME FAILURE				ENGINE FAILURE				CAUSES	
UNIT 9 B & G S		COM. 3		PLACE Mont Joli Aerodrome		DATE 28-1-42		TIME 0900		H.O. FILE 1100-23-3		CAUSES		MISCELLANEOUS	
A/C TYPE Gun Battle		No. 2303		CRAS-CAT. "B"		SE x		ME		DAY x		NIGHT		MISCELLANEOUS	
NAME		RANK		No.		DUTY		INJURIES		SERIOUS		FATAL		INJURY	
Moore, E.D.		F/O		C4348		P.		Uninjured.		SERIOUS		FATAL		INJURY	
Fournier, E.F.		LAC		R98467		A.G.		Uninjured.		SERIOUS		FATAL		INJURY	
Taylor, A.H.		LAC		R97354		A.G.		Uninjured.		SERIOUS		FATAL		INJURY	
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS		STAGE OF FLIGHT	
Battle		2303		Slight								INST. NIGHT		ON TYPE	
Merlin S3HI		4071										7		470	
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE		TOTAL		LAST 6 MOS	
A 22		28-1-42										495			
NATURE OF ACCIDENT															

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Gunnery Exercise.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

**Aircraft taxiing on taxi strip turned
to edge of taxi strip to pass horse
drawn sleigh, running into soft snow.**

Burst of engine and deep snow caused

**nose of aircraft to drop - airscrew
struck ground.**

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Careless taxiing.~~

ACTION TAKEN:

(A) DISCIPLINARY (E) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE