

,))))))))))))))))))) 	/ ,
)	DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER	,
)	Ferrying aircraft from Fingal Ont. OR COMMANDING OFFICER'S REPORT: R170	,
)	to St. Hubert, P.Q. NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: LEC.	
)	Made an attempt to land aircraft COMPOSITION:)
)	amd overshot, on the second attempt	,
)	he landed to the right of No. 1 Run-	,
)	way passed over the East portion of RECOMMENDATIONS:)
,	the edge of No. 2 Runway and overturned	
,	PRIMARY CAUSE:)
))
)	Landed downwind.)
)	1. Querslat ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
)	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
))
)		
)		,
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	,
)	Overshot runway and struck snowbank.	,
)	RECORDED BY DATE)
)	CHECKED BY DATE	i
))