

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																																																																														
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32																																																																														
PILOT										OTHERS										AIRFRAME FAILURE										ENGINE FAILURE																																																																															
CAUSES OF ACCIDENTS																																																																																																													
UNIT 20 E.F.T.S.										COM. 1										PLACE Whitby Aerodrome,										DATE 14-1-42 TIME 1600																																																																															
Oshawa, Ontario,										1										Whitby Aerodrome,										H.Q.F. 1100-49-76																																																																															
A/C TYPE Tiger Moth										NO. 4978										CRASH CAT. C 14										SE x ME x DAY x NIGHT x																																																																															
NAME										RANK										NO.										DUTY										INJURIES										SERIOUS																																																											
Pettit, M.F.										Sgt										2230										T.I.										Uninjured.										FATAL										INJURY																																																	
Adams, R.W.										LAC										R109624										P.P.										Uninjured.																																																																					
TYPE A/F & ENGINE										No.										EXTENT OF DAMAGE										REPORT FORM										SERIAL No.										DATE										HOURS FLOWN BY PILOTS																																																	
T. Moth										4978										Serious																																								INST.										NIGHT										ON TYPE										TOTAL										LAST 6 MOS									
G. Major										7481										N11										N11										---										25										13										25										13																													
SIGNAL No. & DATE										UNIT No. & DATE										COM. No. & DATE										REPORT										FILE										DATE																																																											
A 21										15-1-42																																																																																																			
NATURE OF ACCIDENT																																																																																																													

MISCELLANEOUS CAUSES
 STAGE OF FLIGHT
 HAND Q
 INSTS.
 WEATHER
 DRKNS.
 AL'S SURF.
 OTHER
 UND TD
 PRIMARY
 TAXIING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ.
 INJURY
 SER.

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Cross wind take offs and landings.

OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

09/15/1006

COMPOSITION:

Strong cross wind tipped aircraft on take off - right wing caught ground turning aircraft down wind - aircraft went through fence.

RECOMMENDATIONS:

N11

PRIMARY CAUSE:

~~Inexperience of new instructor in failing to realize strength of wind and limitations of light aircraft in cross wind take offs.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

16. Other

Instructor checked on cross-wind take-offs and landing.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft turned down wind and went through fence.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____