

, , , , , , , , , , , , , ,	, , , , , , , , , , , , , , , , , , ,
Duty on Which Engaged: Landings & take off solo	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: RT70
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Landed A/C with undercarriage up. although red lights were showing.	DATE: COMPOSITION:
)	RECOMMENDATIONS:
)	Nil
PRIMARY CAUSE: Incorrect vital action check, disregarded verog lights.))) ()	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Pupil's log book endorsed by C.O.
secondary cause or contributing factors: 32. We writt - a line Aircraft landed with undercarriage retracted.	RECORDED BY DATE
•	CHECKED BY DATE