

DUTY ON WHICH ENGAGED:

Routine bombind exercises.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Commanding Officer's Report.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Forced landing on airdrome.

Hydraulic line blew on take off filling Pilot's cockpit with heavy hydraulic fluid fumes, causing him to force land on the Aerodrome with Undercarriage retracted.

DATE:

COMPOSITION:

1B/1M/4UH

RECOMMENDATIONS:

Nil.

PRIMARY CAUSE:

1. ~~Failure of pressure line on Hydraulic Pump.~~
2. ~~Pilot's inability to see due to the Hydraulic fluid blinding him, nauseated and partly overcome by fumes.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Hydraulic line pressure checked on all A/C.

15. Forced Land

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft forced landed with Undercarriage retracted.~~

34. Mc Strain

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____