

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Solo flight circuit

OR COMMANDING OFFICER'S REPORT:

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Stbd oleo leg failed during normal landing & A/C ground looped.

COMPOSITION:

100/10001

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Failure of stbd oleo leg~~

2. Seizing

2

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C ground looped damaging V/C &~~

~~Stbd. engine.~~

34 Mc Strain

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____