

CASPIR Aircraft Accident Cards

Serial: DG817

Title: Avro Anson Mk. I serial:DG817 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-March-17. Anson I s/n DG817. This accident involved 2 people. Carpenter PM, Dowsett GF

Keywords: RAFAnson I,DG817,41 SFTS,41 Service Flying Training School,Aerodrome,1942-March-17,Carpenter,DowsettRCAF L20

Created: 1942-03-17

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#DG817>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

~~In~~ **Take offs.**

OR COMMANDING OFFICER'S REPORT:

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

**Taxiing on perimeter of airdrome
STBD U/C went into hole concealed
by ice.**

COMPOSITION:

7M/USG/XSM

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Poor construction of airdrome.~~

10. Bad Ground

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

STBD. U/C collapsed.

34 w/o strain

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____